


FIG.1

FIG. 2






Figure 3A. Positioning errors when two satellite measurements are combined with one RTD measurements




Figure 3B. Positioning Errors when three satellite measurements are combined with one RTD measurements




Figure 3C. Positioning errors when four satellite measurements are combined with one RTD measurements




Figure 3D. Positioning errors when five satellite measurements are combined with one RTD measurements




Figure 3E. Positioning errors when six satellite measurements are combined with one RTD measurements





FIG. 1
PRIOR ART

28-W Gleichstrom Batterie



24 →

26 →

FIG. 2




FIG. 3




FIG. 4